

## Stat of Utah DEPARTMENT OF NATURAL RESOURCES DIVISION OF OIL, GAS AND MINING

355 West North Temple 3 Triad Center, Suite 350 Salt Lake City, Utah 84180-1203 801-538-5340 801-359-3940 (Fax) 801-538-5319 (TDD)

January 27, 1994

TO:

Minerals File

FROM:

Travis Jones, Reclamation Hydrologist 7 W

Tony Gallegos, Reclamation Engineer aa

RE:

Site Inspection, Ecology Mining Co., Deertrail Mine, S/031/005, Piute

County, Utah.

Date of Inspection:

January 11, 1994

Time of Inspection:

4:30 P.M. - 5:15 P.M.

Conditions:

Cool, windy, snow on ground

Participants:

Travis Jones, Tony Gallegos, and Wayne Hedberg, DOGM

Purpose of Inspection: This is an inactive pre-law site that is not currently permitted

with the Division. The purpose of this site visit was to evaluate the status of the mine and document any new developments or

disturbances.

No one was present when we arrived at the site. A track hoe, several pickup trucks and a trommel(?) were new to the site. Tire tracks in the snow behind the gate on the mine property indicated recent activity at the site. The log on the trommel indicated someone had been on-site in August. It appears that some of the old equipment and junk has been removed from the site. The portal entrance has been renovated. Behind the cinder block structures was a new trench leading to freshly poured concrete covered with straw. The road paralleling the power lines and leading past the site had been recently widened by cutting down trees and brush. Photographs were taken to document the status of the site. We did not travel up the widened road leading past the mine site.

jb S031005





































EAR CINCORD ALLETA LETTER CO

U.S. P. U.S.

5/031/005

3/03/005



9/031/005